Rosemary Inn. Dixie Cabin (Bailding No. 383) Olympic National Park Barnes Point, Lake Crescent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-K

HABS WASH 5-POANN,

PHOTOGRAPHS


WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey National Park Service Western Region Department of the Interior San Francisco, California 94107

NATIONAL PARK SERVICE Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY ARCHITECTURAL DATA FORM

| AMSHINATON HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn, "Dixie" Cabin SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 383 COMMETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Farly to mid-1920s (Historic Building Inventory) Loventory) DATE OF CONSTRUCTION (include source) Farly to mid-1920s (Historic Building Inventory) Loventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rursic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rafls; truss system exposed beneating able on west; log enable will be a made and multi-pane casement sash; board and batten siding above logs beneath gable on west; log most set on sadele-notched log rafls; truss system exposed domenting gable on west; log enable will be a made and multi-pane casement sash; board and batten siding above logs beneath gable on west; log enable will be a made and beneath gable on west; log enable gable on west. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacaint OTHER INFORMATION (include listing on National Register, State R | MANINGTON CIALLAM Port Angeles | STATE | COUNTY | | R VICINITY | | |
|--|--|---|---|----------------------------------|----------------------------------|--|--|
| HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn, "Dixie" Cabin MA-185-K SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 383 COMMETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of thwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log pusts set on sadale-notched log rails; truss system exposed beneath gable on west; log ends beveiled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. MITERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Yacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn, "Dixie" Cabin SECONDARY OR COMMON NAMES OF STRUCTURE Bldg, No. 383 COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, pitcuresque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overland supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log apolity or an able on west;. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Structure Report, 1988 Historic Structure Report, 1983 COMPILER, AFFILIATION DATE | | | • ' ' | | | |
| Rosemary Inn | ROSEMARY OR COMMON NAMES OF STRUCTURE ### SIdg, No. 383 **COMPLETE ADDRESS (for rural sites describe location)** Barnes Point, south shore of Lake Crescent, morth side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. **DATE OF CONSTRUCTION (include source)** Early to mid-1920s (Historic Building Inventory) **DATE OF CONSTRUCTION (include source)** Early to mid-1920s (Historic Building Inventory) **SIGNIFICANCE (architectural and historical, include original use of structure)** **DISCONDING TO THE CONTROL OF THE CONTROL | | | | | | |
| SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 383 COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake (rescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rafls; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. NTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Yacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Negister Listing, 1979 Historic Resource Study, 1983 | SECONDARY OR COMMON NAMES OF STRUCTURE bldg. No. 383 COMPILETE ADDRESS (for rural sites describe location) Barnes Proint, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SiGNIFICANCE (architectural and historical, include original use of structural) SiGNIFICANCE (architectural and historical, include original use of structural) This cabin was constructed as an integral part of the Rosemary inn Complex. It contributes to the overall character of the rurstic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overlang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath hable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | | | r name) | | | |
| Edidg. No. 388 COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (Include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, jetturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (If appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overlang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Yacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Structure Report, 1986 National Register Listing, 1979 | COMPILETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. SIYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | | W. 103 K | | |
| COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) BIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) Builder and Craftsman: John Daum (HRS, 1983) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. SIYLE (If appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF SIRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Rusting in the process of the process o | SECONDARY OR COMMON NAMES | OF STRUCTURE | | | | |
| Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west log ends beveiled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) Historic Building and Craftsman: John Daum (HRS, 1983) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | .RJqd• ฟo• 383 | | • | | | |
| Trom Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) Early to mid-1920s (Historic Bullding Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (If appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Structure Report, 1983 | From Port Angeles, in Olympic National Park. DATE OF CONSTRUCTION (include source) | COMPLETE ADDRESS (for rural site | s describe locat | tion) | | | |
| Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Structure Report, 1983 | Early to mid-1920s (Historic Building Inventory) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. SIYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends beveiled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Ruilding Inventory, 1983 COMPILER, AFFILIATION DATE | Barnes Point, south shore of I from Port Angeles, in Olympic | Lake Crescent, National Park | north side of • | Hwy 101, approximately 20 miles | | |
| Inventory) John Daum (HRS, 1983) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction, MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Inventory) John Daum (HRS, 1983) SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends beveiled at notches; diamond-pane and multi-pane casement sask; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Resource Study, 1983 Historic Resource Study, 1983 COMPILER, AFFILIATION DATE | DATE OF CONSTRUCTION (include s | source) | | | | |
| SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shringled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. STAPPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Resource Study, 1983 Historic Resource Study, 1983 COMPILER, AFFILIATION | | | | | | |
| This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | | | | | | |
| contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12 'x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | This capin was constructed as | an integral p | art of the Ros | emary Inn Complex. It | | |
| ASSOCIATION. STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | ASTYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends beveiled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | contributes to the overall cha | aracter of the | rustic, pictu | resque resort ensemble and | | |
| STYLE (if appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | STYLE (If appropriate) Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | , materials, w | orkmanship, lo | cation, setting, feeling and | | |
| Craftsman-style cottage/Rustic MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 | MATERIAL OF CONSTRUCTION (include structural systems) Sadale-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | association. | | | | | |
| MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | MATERIAL OF CONSTRUCTION (include structural systems) Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overlang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; gog ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | STYLE (if appropriate) | | | | | |
| Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | Craftsman-style cottage/Rustic | Ĉ | | | | |
| Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Saddle-notched log construction set on concrete footings; porch set on loose sandstone; bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | MATERIAL OF CONSTRUCTION (In a | | -1 | | | |
| bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 | bath set on concrete slab. SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | Saddle-notched log construction | n ude structural s on set on conc | ystems) rete footinas: | norch set on loose sandstone: | | |
| Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on sadale-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Rectangle: 12' x 27' (overall) EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | 311 300 011 00110 | , e s e ' 1 0 0 2 7 1 1 9 2 3 | porter des en result carragemen, | | |
| EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | SHAPE AND DIMENSIONS OF STRUC | CTURE (sketched | floor plans on | separate sheet acceptable) | | |
| l-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | 1-story; wood-shingled gable roof with extended eaves, exposed log rafter ends, and log fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | Rectangle: 12' x 27' (overall |) | | • | | |
| fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | fascia; roof extended on west facade forms porch overhang supported by rustic log posts set on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | | | | | | |
| on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | on saddle-notched log rails; truss system exposed beneath gable on west; log ends bevelled at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | 1-story; wood-shingled gable i | roof with exter | nded eaves, ex | posed log ratter ends, and log | | |
| at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | at notches; diamond-pane and multi-pane casement sash; board and batten siding above logs beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION | Tascia; root extended on west | Tacade Futilis : Endes evetem e | porch overnany xnosed beneath | able on west: log ends bevelled | | |
| Deneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | beneath gable on west. INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | at notches: diamond-pane and multi-pane casement sash; board and batten siding above logs | | | | | |
| Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 | Painted floor boards; exposed log wall construction. MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | beneath gable on west. | | | | | |
| MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | MAJOR ALTERATIONS AND ADDITIONS, WITH DATES PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | i ' | • | |) | | |
| PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | Painted floor boards; exposed log wall construction. | | | | | |
| PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | | ·· | | |
| PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | | | | |
| PRESENT CONDITION AND USE Fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | PRESENT CONDITION AND USE fair; Vacant OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | MAJOR ALTERATIONS AND ADDITIO | NS. WITH DATES | 3 | | | |
| OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | MAJOR ALIERATIONS AND ADDITIO | Mo, WILL | , | | | |
| OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | | | | |
| OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | OTHER INFORMATION AS APPROPRIATE SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | | | | |
| SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | rair; vacant | | | | | |
| Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION National Register Listing, 1979 National Register Listing, 1979 DATE | OTHER INFORMATION AS APPROPRI | IATE | | | | |
| Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION National Register Listing, 1979 National Register Listing, 1979 DATE | | | | | | |
| Historic Structure Report, 1986 National Register Listing, 1979 Historic Resource Study, 1983 | Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION National Register Listing, 1979 National Register Listing, 1979 DATE | SOURCES OF INCORMATION (include | listing on Natio | nal Register St | ate Registers etc.) | | |
| Historic Resource Study, 1983 | Historic Resource Study, 1983 Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | | Nation | al Register Listing, 1979 | | |
| | Historic Building Inventory, 1983 COMPILER, AFFILIATION DATE | | - - | | | | |
| | · · · · · · · · · · · · · · · · · · · | | 1983 | | | | |
| COMPILER, AFFILIATION DATE | · · · · · · · · · · · · · · · · · · · | COMPILER, AFFILIATION | | <u> </u> | DATE | | |
| | | <u>-</u> | al Park Servic | e | 1 | | |





Dixie Building #383